

BORESCOPE INSPECTION REPORT # 001734

Station DME Data 16.07.2008 A/C Registration EI-DMH ENG.Serial # 716612

Borecope Inspection Performed reason MJSS 154 (WO FROM KRAS AIR)
(MJSS, Special inspection, Reduced interval, e.t.c.)

RESULT

No damages are found during inspection

Acceptable damages (with tolerance) iaw AMM _____ are found _____

Remove engine from service iaw AMM 72-00-00/661 within 5 CYC
(limit in hours or cycles)

Describe damages which are limited engine operation *Borecope has been performed. During inspection on combustion chamber on inner louver at position 12 and 6 o'clock found axial crack connected with circumferential crack with material that is gone. At 6 o'clock position axial crack has length about 37 mm, circumferential crack has length 65,55 mm. IAW AMM 72-00-00/666 this damage are not permitted. IAW AMM 72-00-00/661 maximum 5 cycles to get to a maintenance base.*

Immediate removal of engine iaw AMM _____ is required.

Describe damages causing removal of engine _____

| STATION | REPORT EXECUTED | | |
|---------|-----------------|----------|-------------------|
| | DATE | NAME | SIGNATURE / STAMP |
| DME | 16.07.2008 | IVINSKIY | ELT 196 |